

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

## INSPECTION REPORT

Partial: XXX Com	plete:	Exploration:	
Inspection Date & Time:	5/16/2001	/10:00a.m2:30p.m.	
Date of Last Inspe	ection: 4/I	7/2001	

Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032

Permittee and/or Operator's Name: Genwal Resources, Inc.

Business Address: P.O. Box 1420, Huntington, Utah 84528

Type of Mining Activity: Underground XXX Surface Prep. Plant Other

Company Official(s): Gary Gray

State Official(s): Bill Malencik Federal Official(s): None

Weather Conditions: Partly Cloudy, Temp in upper 60's, dry mine site

Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded

Status: Active XXX

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVAL</b>	UATED	N/A	<b>COMMENTS</b>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE					П
2.	SIGNS AND MARKERS		[X]		[X]	$\Box$
3.	TOPSOIL		[X]	П	[X]	$\Box$
4.	HYDROLOGIC BALANCE:					
	a. DIVERSIONS		[X]		[X]	
	b. SEDIMENT PONDS AND IMPOUNDMENTS		[X]	$\Box$	[X]	$\Box$
	c. OTHER SEDIMENT CONTROL MEASURES		[X]	$\Box$	[X]	$\Box$
	d. WATER MONITORING		[X]	$\Box$	[X]	
	e. EFFLUENT LIMITATIONS		[X]	$\Box$	П	
5.	EXPLOSIVES		[X]	П	$\Box$	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		Ц	Ц	П	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		$\Box$	$\Box$	П	
8.	NONCOAL WASTE		[X]	$\Box$	[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED					
	ENVIRONMENTAL ISSUES		$\Box$	$\Box$	П	$\Box$
10.	SLIDES AND OTHER DAMAGE		[X]		П	$\Box$
11.	CONTEMPORANEOUS RECLAMATION		П		П	$\Box$
12.	BACKFILLING AND GRADING		$\Box$		П	$\Box$
13.	REVEGETATION		[X]	$\Box$	Ц	
14.	SUBSIDENCE CONTROL		$\Box$	$\Box$		
15.	CESSATION OF OPERATIONS		$\Box$	$\Box$		
16.	ROADS:					
	a. CONSTRUCTION/MAINTENANCE/SURFACING		[X]	$\Box$	П	$\Box$
	b. DRAINAGE CONTROLS			$\Box$	П	$\Box$
	OTHER TRANSPORTATION FACILITIES		$\Box$	$\Box$	П	$\Box$
	SUPPORT FACILITIES/UTILITY INSTALLATIONS		$\Box$	$\Box$	$\Box$	
	AVS CHECK (4th Quarter- April, May, June)		$\Box$	П	$\Box$	$\Box$
	AIR QUALITY PERMIT		$\Box$	$\Box$	$\Box$	$\Box$
	BONDING & INSURANCE				$\Box$	$\Box$
22.	OTHER: USFS SILT FENCES		[X]	$\Box$	[X]	П

## **INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/015/032

DATE OF INSPECTION: 5/16/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

## **GENERAL COMMENTS**

A partial inspection was completed at the office and at the mine on 5/16/2001. No violations were issued as a result of this inspection.

#### 2. SIGNS AND MARKERS

The mine and permit identification sign is located at the permit boundary just below the mine site. The markers include: stream buffer zone, disturbed area, and topsoil markers.

#### 3. TOPSOIL

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by berms and/or silt fences. The operator plans on submitting an amendment. This will be done after a vegetal study is performed by the mine. The mine objective is to demonstrate that the vegetal cover meets the Division standards, and therefore, the silt fences can be removed. Mr. Gray stated he will contact Pat Collins to perform the necessary studies. Hopefully, this can be done in June 2001.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were checked. They were found to comply with the requirements of the Mining and Reclamation Plan and the Coal Rules performance standards with the exception noted below.

The off slope pond drainage below the Jersey barriers was bermed to divert the runoff into the pond. This was noted as a follow-up to the last inspection.

## 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was not discharging during the inspection. The pond has never discharged.

The operator has received a review of the midterm. The midterm was dated February 26, 2001. Rechecked with Gary Gray and he stated the midterm review, as you approved it, was sent in 5/25/2001. Further, he advised me that the amendment was received 5/29/2001 at 9:00 a.m. by Velasquez.

# 4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Snow storage area is void of snow. This area has been approved by the Division and the Forest Service.

## **INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/015/032

DATE OF INSPECTION: <u>5/16/2001</u>

## 4D. HYDROLOGIC BALANCE: WATER MONITORING

Eric Peterson is now doing the water monitoring for Crandall Canyon. This included five streams, five in-mine wells, and fourteen springs. This also included field and laboratory measurements.

The first quarter monitoring was reviewed by the undersigned. The first quarter results, according to Mr. Gray, have been e-mailed to the Division for inclusion into the data base. The second quarter samples for the lower sites have been taken and have been sent to the laboratory. The results have not been received. The higher sites will be taken next week now that the upper sites are not snow-covered.

# 8. NONCOAL WASTE

The non-coal waste storage area is clean. No non-coal waste was observed in other disturbed areas.

## 22. OTHER: USFS SILT FENCES

The USFS silt fences, that are located before the USFS road, have been cleaned since the last inspection.

Inspector's Signature: Date: May 24, 2001
Wm J. Malencik #26

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Gary Gray, Genwal

Price Field office

O:\015032.CRA\Compliance\2001\p\_0516.wpd